Insp. No: 2017-08-29-11:01 Inspector(s): El Paso / Chas J + Fernandez
Insp. Date: 8/29/17 Insp. Time: 11:05

Information for Facility Where Inspection Occurred

Facility Name: Price Daniel Facility Type:
Address 1: POC: ~~COOK~~ HANNA
Address 2: POC Title: Chief
City/State: Zip:
CBP POC: COOK CBP Phone:

Importer Information (from Entry Documents)

Company or Name: HISUN Entry No: 96C-0282141-1
Address: Importer No: 27-249338066
Address 2: Entry Date: 8/29/17
City: Quantity (engine family): ~~500~~ 520
State: Zip: Quantity (model):
Importer POC: Phone:

Box Information

VIN/ESN: LWSGML04HA0P3398 MFG on Box: ~~CF~~ / Coleman
Model indicated: KT196 Date of MFG: 8/7/17 Other Info on box:
49 or 50 State Certified: ☐ 49 ☐ 50 ☐ NR Power: 6.5 ☒ hp ☐ kW Displacement: 196 ☒ cc ☐ ci ☐ liter

ECI Information

Label Present: ☐ Y ☐ N MFG on ECI: Chongqing Hisun Science & Tech Ind. Ltd
Engine Family: HHSNX.196T.K1 Certificate Holder on ECI: Hisun Motors Corp, USA
Evap. Emissions Family: 49 or 50 State Certified: ☐ 49 ☒ 50
Date of MFG: 2017 Emission Control Devices Listed: 2017
Tune-up Specs Listed: ☒ Y ☐ N Power: N/D ☐ hp ☐ kW Displacement: 196 ☒ cc ☐ ci ☐ liter
Does ECI Contain an Exhaust Compliance Statement: ☒ Y ☐ N MY Standards in Exh. Compliance Statement: 4 2017
Does ECI Contain an Evap. Compliance Statement: ☒ Y ☐ N MY Standards in Evap. Compliance Statement: 2017
Can ECI label be removed without destroying: ☐ Y ☒ N <-- *if yes, document with photos* Type of Fuel: GAS.
ECI Notes: Perm. Fam HHSNPMETALA1

Visual Inspection Information

Headlight(s): ☐ Y ☒ N Turn Signal: ☐ Y ☒ N Horn: ☐ Y ☒ N Mirror: ☐ Y ☒ N Tail/Brake Light: ☐ Y ☒ N
Model name: KT196 Exhaust Emission Control Devices Observed: Pair muffler
VIN/ESN: LWSGML04HA0P3398 Removable Hang-tag (MFG, model/engine, normalized emission rate): ☒ Y ☐ N
Fuel Tank Material: METAL Running loss line observed (gasoline engines only)? ☐ Y ☒ N
Fuel lines marked: Yes Crankcase vented to atmosphere: ☐ Y ☒ N

Unless there's an obvious compliance issue, the following measurements only need to be completed if time permits.

Fuel tank size: ☐ gal ☐ L. Fuel hose length (fuel tank to cut-off): ☐ in ☐ mm
Fuel hose Dia. (inner): ☐ in ☐ mm Fuel hose length (cut-off to engine): ☐ in ☐ mm
Fuel hose Dia. (outer): ☐ in ☐ mm Total fuel hose length: ☐ in ☐ mm

	Observed PN	Certified PN		Observed PN	Certified PN
Fuel Tank:			Muffler/Catalyst:		
PAIR:			Fuel Injector:		
Carburetor:			Intake Assembly/Filter:		
Throttle Body			Oxygen Sensor:		
Other:			Spark Plug:		

Visual Inspection Notes: Fuel Cap doesn't close

Owner's Manual Information

Listed Model(s): KT196 Vehicle/Equipment Weight: 120 Units: kg
Emissions Warranty? If Yes, how long?: Yes. ~~Rated~~ Max Power: 5 [X] hp [ ] kW
Min. Warranty under Regs. (after insp.): ~~Rated~~ Max Power RPM: 3600 (e.g., @ 7,000 rpm)
Engine Displacement: 196 cc Type of Fuel: Unleaded (e.g., 91 octane, ULSD)

Carburetor Inspection

A/F mixture screw inspection should be completed for all types of engines (using hand tools only).

Carburetor ID Marking, Manufacturer , logo, numbers, etc.: E191610017052201158
air/fuel mixture screw adjustable on vehicle (*check for all SI engines*)? NO
If A/F screw is adjustable, obtain photograph of inspector adjusting it.
If so, describe the range of adjustability:
Tools needed to adjust a/f screw: Time required:
Tools needed to remove a/f screw: Time required:
Main jet, pilot jet, and jet needle inspection should be only be completed for recreational V&E's (using hand tools only).
Tools needed to access the main jet, pilot jet, jet needle:
Time required to adjust jet needle: No. of positions: Markings: Huayi
Time required to remove main jet: Time to install: Markings:
Time required to remove pilot jet: Time to install: Markings:
Carb. Inspection Notes: Designed in Japan E191610017052201158

Certification Application Information

Cert. Holder/Importer: Hisun Motors. MFG:
Regulatory Category: ATV Regulatory Sub-Category:
Engine Family: ~~HHSNPHETA~~ A1 Cert. Date Range:
Evap./Perm. Family: HHSNPMETALA1 Exhaust Emission Control Devices on Cert. App.:
Carb. adjustments: If plastic fuel tank, is it fluorinated? [ ] Y [ ] N [ ] N/A
49 or 50 State Certified: [ ] 49 [ ] 50 [ ] NR Running loss line (gasoline engines only)? [ ] Y [ ] N [ ] N/A
Rated Power: [ ] hp [ ] kW Rated Power RPM: Displacement: [ ] cc [ ] ci [ ] liter

Inspection Summary

Evidence taken (indicate how it was marked): Exhaust System marked by VIN
Areas of Concern: No warranty period or listed for 2014 / Pending market Result
Inspection photo numbers: 5425 – 5472
Additional Inspection/analysis done on (date):
Inspectors: Photographer:
Inspector Signature: Date:

Guidance for Inspectors:

Inspector should obtain copies of the following when conducting inspections for CBP:

- Entry documents
- Invoice/Packing lists
- Bill of lading
- VIN list
- EPA declaration form (3520)

Inspector should obtain the following key photographs:

- All sides of box that the unit is contained in (include close-up photos of labels on boxes)
- All sides of vehicle/engine to include any labels, model names, or trade names.
- Removable hang-tag (MFG, model/engine, normalized emission rate)
- Emission control label
- Engine serial number engraved on engine and/or VIN engraved on frame
- Owner's manual - front page, specification table, emissions warranty statement
- As equipped (obtain photographs of part numbers for each if possible):
  - o Carburetor - include A/F mixture screw (if carbureted)
  - o Exhaust system (include muffler or any bulges in exhaust pipe)
  - o Crankcase ventilation system
  - o Throttle body (if fuel injected)
  - o Oxygen Sensor (if fuel injected)
  - o PAIR
  - o Fuel lines
  - o Fuel tank
  - o Running loss line

Possible ECDs:

OC Oxidation catalyst
TWC Three-way catalyst
CFI Continuous fuel injection
AIR Secondary air injection (pump)
PAIR Pulsed secondary air injection
MFI Multi-port (electronic) fuel injection
DFI Direct fuel injection
O2S Oxygen sensor
TBI Throttle body (electronic) fuel injection
HO2S Heated oxygen sensor
EM Engine modification